

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
5	BRS	L16	8837	clock same driver and (integrated adj circuit)	USPAT; US-PGPUB; DERWENT	2003/02/10 11:13			0
6	BRS	L20	1952	clock same driver and (integrated adj circuit) and interconnect	USPAT; US-PGPUB; DERWENT	2003/02/10 11:13			0
7	BRS	L28	10	(clock same grid) same driver and (integrated adj circuit) and interconnect and skew	USPAT; US-PGPUB; DERWENT	2003/02/10 11:16			0
8	BRS	L32	7	(clock same grid) same driver and (integrated adj circuit) and interconnect and skew and transmission	USPAT; US-PGPUB; DERWENT	2003/02/10 11:14			0
9	BRS	L24	556	clock same driver and (integrated adj circuit) and interconnect and skew	USPAT; US-PGPUB; DERWENT	2003/02/10 11:22			0
10	BRS	L36	97	clock same driver and grid and (integrated adj circuit) and interconnect and skew	USPAT; US-PGPUB; DERWENT	2003/02/10 11:23			0